

**Coalition for a
Better St Catharines**

The city is yours



Visual Evidence of Asbestos at the Former GM Property

A photograph showing the interior of a half-demolished building. The walls and ceiling are covered in peeling white and light blue paint, revealing a rusty metal structure underneath. Several vertical support columns are visible, some with remnants of blue and yellow paint. In the background, a large pile of debris, including bricks, concrete, and other building materials, is visible. A yellow barrel is also present among the rubble. The scene is set outdoors, with trees and a clear sky visible through the open structure.

Asbestos has been observed throughout the site: in the half-demolished buildings, the debris piles and on the ground.

Asbestos abatement has
not been completed.
Asbestos wrapped pipes
are still in place.



Asbestos wrapped pipes
are damaged in many
places.





Asbestos abatement has not been completed. Degraded asbestos wrapped pipes are still in place.

Asbestos abatement has not been completed. Exposed asbestos wrappings are evident in several buildings.



An elbow joint wrapped in asbestos lies on the ground on the west side of Ontario Street.



Asbestos abatement has not
been completed.

CAUTION
CONTAINS
ASBESTOS





Possible asbestos-based
fibrous building material in
this debris pile.



Photo of asbestos fibreboard from the
[Environmental Abatement Council of Ontario:](#)
[EACO](#) on left.

Suspected asbestos fibreboard at the GM site
on the right.



EACO photo of asbestos pipe on the left
On the right is suspected asbestos pipe
in one of the GM Property debris piles.

